



FIGURE 1





Plane Stress Fracture Toughness (Kapp) of C433-T39 and 2324-T39 Plate in L-T Orientation

